




MANUAL FOR INVISIBLE SPLICE CONNECTOR


Article: 485-085

1. For a secure and watertight connection, slide a heat shrink tube over one the rope lights as a first step.
2. Press all 4 pins of the connector into the main cores of the rope light (images 1 & 2).
3. Now move the heat shrink tube to cover the connector (image 3).
4. Using the heat from a hair dryer, shrink the heat shrink tube until it wraps tightly around the connector/rope light.


1.



2.



3.



4.



Imported by Tronix Lighting, Uden, The Netherlands

No part of this publication may be reproduced or published by means of photocopy, microfilm, any form of digital storage or in any other way without the prior written permission of the publisher.